


Customer:	xxxxxxx				
Site:	-				
Job No:	130128A				
Action Note No:	XXX 13-006				
Panel ID No.:	EPS 0027	Fault temperature, °C:	63.8		
Machine Tag No.:	P01001	Reference temperature, °C:	45.3		
Description:	Tower 2 Propeller Pump		Ambient temperature, °C:	23.0	
Date Raised:	16/09/13		Load, Amps:	80	
Report By:	Andy Mellor		Full Load Current, Amps:	85	
Contact No:	07913-493151		Rise over Reference at FLC, °C:	20.6	
E-Mail:	andy.mellor@pmar.co.uk		Max temp at FLC, 25°C Ambient, °C:	70.5	
Asset Health	 Serious 	 IR Visual	 Serious OK	 UE Other	 NS NS
Report:	<p>Significant temperature rise on brown phase between inverter and contactor. Hottest temperature is at connection to contactor but connection to inverter also shows temperature rise (see over for additional images). Phase currents compared and found to be 79 A (Brown) & 81 A (Black & Grey). The maximum projected temperature is at the limit for PVC insulation. Exact cause uncertain as thermal profile does not match expected profile from poor connection.</p>				
Images:					
Recommendations:	<p>In the first instance, check at both inverter and contactor for: 1) loose connection, 2) improperly made crimped connections. Suggest replacement cable is made up and installed in order to minimise pump downtime.</p>				
Feedback:	<p>Please provide feedback following remedial action:</p>				

<p>53.1°C FLIR 12/09/13 12:24</p> <p>25 52</p>	<p>29.9°C FLIR 12/09/13 12:24</p> <p>25 43</p>	<p>31.4°C FLIR 12/09/13 12:24</p> <p>25 38</p>
<p>Connection to Inverter, Brown phase</p>	<p>Connection to Inverter, Black phase</p>	<p>Connection to Inverter, Grey phase</p>
	<p>63.8°C FLIR 12/09/13 12:24</p> <p>26 63</p>	
<p>Close-up of contactor and bottom of inverter</p>	<p>Connection to top of contactor, Brown phase (left) and Black phase (right)</p>	
<p>43.9°C FLIR 12/09/13 12:23</p> <p>26 46</p>		
<p>Connections to bottom of contactor, Brown phase is at left</p>	<p>Close-up of contactor</p>	